



# M12 Temperature Sensors (Celsius)

TA202, TA204, TA284

## Applicable Sensors



## Temperature Output



## Key Details

V<sub>OUT</sub> at 25 °C = 750 mV ±1 °C  
Measurement Range = -40 °C to 121 °C  
V<sub>OUT</sub> Tolerance (-40 °C to 0 °C) = +4 °C/-2 °C  
V<sub>OUT</sub> Tolerance (70 °C to 125 °C) = +4 °C/-2 °C  
V<sub>OUT</sub> Tolerance (0 °C to 70 °C) = ±2 °C