



M12 Temperature Sensors (Celsius)

TA202, TA204, TA284

Applicable Sensors



Temperature Output



Key Details

V_{OUT} at 25 °C = 750 mV ±1 °C
Measurement Range = -40 °C to 121 °C
V_{OUT} Tolerance (-40 °C to 0 °C) = +4 °C/-2 °C
V_{OUT} Tolerance (70 °C to 125 °C) = +4 °C/-2 °C
V_{OUT} Tolerance (0 °C to 70 °C) = ±2 °C